Siemens:

How to manually shim if you have poor fat suppression

➜ Have series that you want to manually shim prescribed & open

➜ Options (top tool bar)

➜ Adjustments

- A new window will open

➜ Click "Show" on the bottom right

➜ Click "Invalidate All"

➜ Click "Adjust All"

➜ Click Update Info

➜ All areas should be green (no red flags)

➜ Close

➜ Apply your series

➜ Still need to check & possibly adjust fat-water peaks